


WIRING DIAGRAM



SWITCH CONTINUITY

IGNITION SWITCH	
	BAT1 IG TL1 TL2 P
OFF	
ON	
P	

STARTER SWITCH	
	BAT3 HL BAT2 ST
FREE	
PUSH	

ENGINE STOP SWITCH	
	BAT2 IG
OFF	
RUN	
OFF	

TURN SIGNAL SWITCH	
	W R L P PR PL
R	
N	
L	

DIMMER SWITCH	
	HL Lo Hi
Lo	
(N)	
#F	

HORN SWITCH	
	HO E
FREE	
PUSH	

- Br Brown
- Bk Black
- W White
- LG Light Green
- R Red
- G Green
- Y Yellow
- B Blue
- Gr Grey
- LB Light Blue
- O Orange
- P Pink